

In the Specification:

Please amend the Specification as follows:

Please replace the paragraph beginning on page 3, line 5, with the following rewritten paragraph:

Along with the recent increase in resolution of liquid crystal display devices, the numbers of output lines GL1 to GLn and GR1 to GRn of the scanning drivers 101a and 101b are increasing. As a consequence, defects ~~on~~during the manufacturing process readily occur in the scanning drivers 101a and 101b at high probability.

Please replace the paragraph beginning on page 6, line 7, with the following rewritten paragraph:

Furthermore, as shown ~~in~~in Fig. 25, the output line GR2 may short-circuit at a short-circuit point 113 in the second scanning driver 101b, and simultaneously, a scanning line may be disconnected at a disconnection point 114 in the display area 100. In this case, assume that a high-level voltage is applied to the control signal terminal CL, and a low-level voltage is applied to the control signal terminal CR to correct the short-circuit point 113, as described above.